

15A NCAC 02D .2619 ARSENIC, BERYLLIUM, CADMIUM, HEXAVALENT CHROMIUM

(a) Method 29 of Appendix A to 40 CFR Part 60 shall be used to show compliance for arsenic, beryllium, cadmium, and hexavalent chromium metals emission standards.

(b) SW-846 Test Method 3060 shall be used to differentiate hexavalent chromium from total chromium. EPA publication SW-846, "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," is incorporated by reference including subsequent amendments or editions. A copy of chapters, methods, and supporting documents for SW-846 may be obtained free of charge via the Internet from the EPA website at <http://www.epa.gov/hw-sw846/sw-846-compendium>.

*History Note: Authority G.S. 143-215.3(a)(1); 143-215.65; 143-215.66; 143-215.107(a)(5);
Eff. June 1, 2008;
Readopted Eff. November 1, 2019.*